

No	Type	Set of tips	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Charger available	Article code (Charger)	Version of phone software used to test / Comments
1	Apple iPhone	A/E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.07	3.0 (7A341)
2	Apple iPhone 3G	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.07	4.2.1 (8C148)
3	Apple iPhone 3GS	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.07	6.1.2 (10B146)
4	Apple iPhone 4	A/E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.07	7.0 (11A465)
5	Apple iPhone 4S	A/E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.07	7.1.1 (11D201)
6	Apple iPhone 5	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.08	7.0 (11A465)
7	Apple iPhone 5c	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.08	7.1.1 (11D201)
8	Apple iPhone 5s	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.08	7.1.1 (11D201)
9	Apple iPhone 6	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.08	8.0.2 (12A405)
10	Apple iPhone 6s	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.08	10.0.1 (14A403)
11	Apple iPhone 7	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.08	10.0.3 (14A551)
12	Apple iPhone 8	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.08	11.0.3 (15A432)
13	Apple iPhone SE	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.08	9.3.2 (13F69)
14	BlackBerry 8100 Pearl	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	V4.5.0.69 (PI2.7.0.72)
15	BlackBerry 8110 Pearl	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	V4.5.0.55 (PI 2.7.0.68)
16	BlackBerry 8520 Curve	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V4.6.1.286 PI 4.2.0.122
17	BlackBerry 8800	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	V4.5.0.174 (PI 2.7.0.105)
18	BlackBerry 9100 Pearl	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V5.0.0.696 (Platform 6.2.0.57)
19	BlackBerry 9105 Pearl	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V5.0.0.696 (Platform 6.2.0.57)
20	BlackBerry 9320 Curve	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v7.1.0.714 (Platform 9.49.0.76)
21	BlackBerry 9360 Curve	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v7.1.0.234 (Platform 9.6.0.36)
22	BlackBerry 9500 Storm	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v4.7.0.41 PI 4.0.0.40
23	BlackBerry 9520 Storm2	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V5.0.0.497 PI 4.2.0.220
24	BlackBerry 9700 Bold	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v5.0.0.979 PI 5.1.0.178
25	BlackBerry 9780 Bold	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v6.0.0.668 PI 6.6.0.236
26	BlackBerry 9800 Torch	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v6.0.0.534 PI 6.6.0.200
27	BlackBerry 9860 Torch	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V7.1.0.746 PL 5.1.0.546
28	BlackBerry 9900 Bold Touch	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v7.0.0.585 (Platform 5.0.0.734)
29	BlackBerry Q5	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v10.2.1.537
30	BlackBerry Q10	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	10.2.1.3175
31	BlackBerry Q20 Classic	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	v10.3.2.2836
32	BlackBerry Z10	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	10.2.1.2102
33	BlackBerry Z30	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	10.2.1.3062
34	CAT (Caterpillar) B15	B	✓	✓	✓	✓ ₁			4.1.2
35	HTC 7 Mozart	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WP 7.5 Radio 5.71.09.02a_22.51.50.21U
36	HTC 7 Pro	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WP 7.5 Radio 5.71.09.02a_22.51.50.21U
37	HTC Desire S	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android OS 2.3.5 2.10.401.8
38	HTC Desire X	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android OS 4.1.1 sw. Nr. 2.23.118.2
39	HTC Desire Z	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android OS 2.3.3 sw. Nr. 2.42.405.4
40	HTC Desire 310	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android OS 4.2.2 sw. Nr. 1.00.118.4
41	HTC EVO 3D X515m	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android OS 4.0.3 sw. Nr. 3.28.401.1
42	HTC Incredible S	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.0.4 sw.4.10.405.1
43	HTC Legend	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android OS 2.2 sw. Nr. 3.14.161.1
44	HTC Magic	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	1.5

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓₁ only from phone

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Type	Set of tips	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Charger available	Article code (Charger)	Version of phone software used to test / Comments
45	HTC One	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.2.2 4.20.111.21
46	HTC One S	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.1.1 3.16.111.10
47	HTC One V	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.0.3 2.22.111.10
48	HTC Sensation	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android OS 4.0.3 sw. Nr. 3.33.111.51
49	HTC Touch2	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	5.2.21854 (21854.5.0.80)
50	HTC Touch DIAMOND 2	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	Radio 2.53.407.6 (76952) GER
51	HTC Touch Dual	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	1.31.407.09 Radio 1.58.16.27
52	HTC Touch HD	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	ROM: 1.14.407.3 (22273) GER
53	HTC HD mini	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	ROM: 1.36.479.1 (94538) WWE
54	HTC HD2	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	3.14.407.2 (04666) GER
55	HTC HD7	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WP 7.5 Radio sw:5.71.09.02a_22.51.50.21U
56	HTC Touch Pro2	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.02	Radio 2.07.407.1 (80303) GER
57	HTC Wildfire	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 2.2.1 2.24.162.1
58	HTC Windows Phone 8X	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WP 8 Radio sw:1.20b.32.19.04_15.67b.32.19
59	HUAWEI Ascend P1 U9200	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.0.3 U9200-1V100R001C00B219
60	LG E960 Nexus 4	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.4.3 KTU84L
61	LG Nexus 5	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.4.4 KTU84P
62	LG G2 D802	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.2.2 D80210a-262-01
63	LG G2 mini LTE (D620r)	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.4.2 V10c-260-01
64	LG KM 900 Arena	E	✓	✓	✓	✓ ₁			KM900AT_V10t
65	LG P710 Optimus L7 II	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.1.2 SW LG-P71010e-EUR-XX
66	LG P760 Optimus L9	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.1.2 SW LG-P76020c-EUR-XX
67	LG P880 Optimus 4X HD	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.1.2 SW LG-P88020b-232-10
68	LG P970	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 2.3.4 SW LG-P970-V20h
69	LG Optimus 2X (P990 Optimus Speed)	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 2.2.2 SW LGE LGP990-V10e
70	Microsoft Lumia 532 Dual SIM	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WP 8.1 Update SW 20c9.00076.0001
71	Microsoft Lumia 535	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WP 8.1 Update SW 20c9.00076.0001
72	Microsoft Lumia 535 Dual SIM	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WP 8.1 Update SW 20c9.00076.0001
73	Microsoft Lumia 550	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WP 10 Mobile SW 01078.00037.16082.41022
74	Microsoft Lumia 640 Dual SIM	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WP 8.1 Update 2 SW 20c9.00072.0001
75	Microsoft Lumia 640	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	
76	Microsoft Lumia 640 LTE	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	
75	Microsoft Lumia 650	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WP 10 Mobile SW 01078.00037.16082.41010
76	Motorola DEFY (MB525)	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	34.906.1.mb525.t-Mobile.en.DE
77	Motorola DEFY+ (MB526)	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 2.3.6 45.0.2310.MB526.Retail.en.DE
77	Motorola G	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	
78	Motorola Milestone	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 2.2.1
79	Motorola Motoluxe (XT615)	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 2.3.7 NK: 1_67C_4035
80	Motorola RAZR i XT890	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.1.2 9.8.21-50_SMI-26.1358455837
81	Nokia 208.1	E	✓	✓	✓	✓ ₁			V06.01
82	Nokia 500	E	✓	✓	✓	✓ ₁			Symbian Belle 111.020.0059
83	Nokia 515	E	✓	✓	✓	✓ ₁			V 07.01
84	Nokia 3109c	F	✓	✓	✓	✓ ₁			V07.21
85	Nokia Asha 300	E	✓	✓	✓	✓ ₁			V 07.57

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓₁ only from phone

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Type	Set of tips	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Charger available	Article code (Charger)	Version of phone software used to test / Comments
86	Nokia Asha 311	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V 05.92
87	Nokia C2-01	E	✓	✓	✓	✓ ₁		0-07-0258-0.04	V 11.40
88	Nokia C3-00	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.04	V 08.63
89	Nokia C3-01 Touch and Type	E	✓	✓	✓	✓ ₁			V 07.15
90	Nokia C5-00 5MP	E	✓	✓	✓	✓ ₁			V 073.001
91	Nokia C5-03	E	✓	✓	✓	✓ ₁			V 23.0.015
92	Nokia C6	F	✓	✓	✓	✓ ₁			V 42.0.004
93	Nokia C7-00	E	✓	✓	✓	✓ ₁			V 012.003
94	Nokia E5-00	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.04	V 071.003
95	Nokia E6-00	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Symbian Belle V 111.140.0058
96	Nokia E7-00	A'	✓	✓	✓	✓ ₁			Symbian Belle V 111.030.0609
97	Nokia E72	E	✓	✓	✓	✓ ₁			081.003
98	Nokia Lumia 520	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Windows Phone 8.0 SW 2.0.242020.8
99	Nokia Lumia 610	F	✓	✓	✓	✓ ₁		0-07-0258-0.01	Windows Phone 7.5 Radio sw:1.0.66.00
100	Nokia Lumia 625	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Windows Phone 8.0 Radio sw:3.2.28060.7
101	Nokia Lumia 635	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WP 8.1 Update Radio sw:201c1.00401.0001
102	Nokia Lumia 820	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Windows Phone 8.0 Radio sw:1.0.202158.3
103	Nokia Lumia 900	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Windows Phone 7.5 Radio sw:2.1.75.25
104	Nokia Lumia 920	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Windows Phone 8.0 Radio sw:1.0.202158.3
105	Nokia Lumia 925	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Windows Phone 8.0 Radio sw:3.2.04033.1
106	Nokia Lumia 930	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WP 8.1 Update Radio sw:201c110.00039.0001
107	Nokia Lumia 1020 (909)	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	WP 8.0 Radio sw:3.2.04047.1
108	Nokia N8	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Symbian Belle V 111.040.1511
109	Nokia N9	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V 40.2012.21-3.342.01.1_PR_342
110	Nokia N97	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V 22.0.110
111	Nokia N900	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V21.2011.38-1
112	Nokia X6	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	V 40.0.002
113	Nokia X7-00	A'	✓	✓	✓	✓ ₁			Symbian Belle V 111.040.1511
114	Samsung B2100	F	✓	✓	✓	✓ ₁			B2100XXHL1
115	Samsung B2700	F	✓	✓	✓	✓ ₁			B2700XXIB2
116	Samsung B7330 OmniaPro	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	B7330XXIG2
117	Samsung B7610 OmniaPro	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	B7610XXIK2
118	Samsung C6625	E	✓	✓	✓	✓ ₁			C6625BUIE1
119	Samsung G386F Galaxy Core LTE	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.2.2 JDQ39.G386FXXUANB4
120	Samsung G388F Galaxy Xcover 3	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.4.4 KTU84P.G388FXXU1AOG4
121	Samsung G800F Galaxy S5 mini	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.4.2 KOT49H.G800FXXU1IANJ2
122	Samsung G900F Galaxy S5	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.4.2 KOT49H.G900FXXU1ANE2
123	Samsung G903F Galaxy S5 Neo	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G903FXXU1BPF4
124	Samsung G920F Galaxy S6	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 5.0.2 LRX22G.G920FXXU1AOCV
125	Samsung G925F Galaxy S6 edge	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 5.0.2 LRX22G.G925FXXU1AOCV
126	Samsung G930F Galaxy S7	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G930FXXU1APC8
127	Samsung i7500 Galaxy	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	I7500XXMC2
128	Samsung I8000 Omnia II	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	I8000XXII6
129	Samsung I8150 Galaxy W	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	I8150XXLMI

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓₁ only from phone

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Type	Set of tips	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Charger available	Article code (Charger)	Version of phone software used to test / Comments
130	Samsung I8160 Galaxy Ace 2	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	I8160XXLL2
131	Samsung I8190 Galaxy S III mini	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.1.2 I8190XXAMG4
132	Samsung i8320 Vodafone 360 H1	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.1.2 I8190XXAMG4
133	Samsung I8700 Omnia 7	A'	✓	✓	✓	✓ ₁			WP 7.5 Radio sw:2424.11.9.4
134	Samsung I8750 Ativ S	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Windows Phone 8.0 Radio sw: 2424.13.5.1
135	Samsung i8910 Omnia HD	B	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	I8910XXJA1
136	Samsung I9000 Galaxy S	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	I9000XXJW4
137	Samsung I9001 Galaxy S Plus	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 2.3.6 I9001XXKPO
138	Samsung I9100 Galaxy S II	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.1.2 I9100XXMS2
139	Samsung I9195 Galaxy S 4 mini	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.2.2 I9195XXUBM7
140	Samsung I9300 Galaxy S III	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.3 sw: I9300XXUGNA8
141	Samsung I9305 Galaxy S III Lte	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.4.4 KTU84P.I9305XXUFOA1
142	Samsung I9505 Galaxy S4	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 4.2.2 sw: JDQ39.I9505XXUAMDM
143	Samsung J320F Galaxy J3 (2016)	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	Android 5.1.1 LMY47V.J320FXXS0QA1
144	Samsung S5230 Avilla	E	✓	✓	✓	✓ ₁			S5230BVIE3
145	Samsung S5260 Star II	E	✓	✓	✓	✓ ₁			S5260XXKC4
146	Samsung S5570i Galaxy Mini	F	✓	✓	✓	✓ ₁	0-07-0258-0.01		Android 2.3.6 sw: S5570IXXLD6
147	Samsung S5611	E	✓	✓	✓	✓ ₁	0-07-0258-0.01		
148	Samsung S5690 Galaxy Xcover	A'	✓	✓	✓	✓ ₁			Android 2.3.6 sw: S5690XXLL1
149	Samsung S6500 Galaxy mini 2	E	✓	✓	✓	✓ ₁	0-07-0258-0.01		Android 2.3.6 sw: S6500XXLK2
150	Samsung S7220	E	✓	✓	✓	✓ ₁	0-07-0258-0.01		S7220XXIB7
151	Samsung S7500 Galaxy Ace Plus	E	✓	✓	✓	✓ ₁	0-07-0258-0.01		Android 2.3.6 sw: S7500XXMC2
152	Samsung S7560 GalaxyTrend(Ace II X)	A'	✓	✓	✓	✓ ₁	0-07-0258-0.01		Android 4.0.4 sw: S7560XXAMEA
153	Samsung S7580 Galaxy Trend Plus	A'	✓	✓	✓	✓ ₁	0-07-0258-0.01		Android 4.2.2 JDQ39.S7580XXUBOA1
154	Samsung S7710 Galaxy Xcover 2	A'	✓	✓	✓	✓ ₁			Android 4.1.2 sw: S7710XXAMB5
155	Samsung S8000 Jet	E	✓	✓	✓	✓ ₁	0-07-0258-0.01		S8000XXIF5
156	Samsung S8300V	E	✓	✓	✓	✓ ₁	0-07-0258-0.01		S8300BUIC6
157	Samsung S8500 Wave	E	✓	✓	✓	✓ ₁	0-07-0258-0.01		S8500XXLA1
158	Samsung S8530 Wave II	A'	✓	✓	✓	✓ ₁			S8530XXLA1
159	Samsung S8600 Wave 3	A'	✓	✓	✓	✓ ₁	0-07-0258-0.01		S8600XXLD1
160	Samsung SGH-i900 OMNIA 8GB	F	✓	✓	✓	✓ ₁			i900XXIB2
	Samsung SGH-i900 OMNIA 16GB								i900BOHH2
161	Samsung Xcover 271 (B2710)	F	✓	✓	✓	✓ ₁	0-07-0258-0.01		B2710BOJJ3
162	SONY Xperia E (C1505)	E	✓	✓	✓	✓ ₁	0-07-0258-0.01		Android 4.1.1 sw 11.3.A.2.23
163	SONY Xperia J (ST26i)	A'	✓	✓	✓	✓ ₁	0-07-0258-0.01		Android 4.1.2 sw 11.2.A.0.31
164	SONY Xperia M (C1905)	A'	✓	✓	✓	✓ ₁	0-07-0258-0.01		Android 4.3 sw 15.4.A.1.9
165	SONY Xperia P (LT22i)	A'	✓	✓	✓	✓ ₁			Android 4.1.2 sw 6.2.A.1.100
166	SONY Xperia S (LT26)	A'	✓	✓	✓	✓ ₁	0-07-0258-0.01		Android 4.0.4 sw 6.1.A.2.45
167	SONY Xperia SP (C5303)	A'	✓	✓	✓	✓ ₁	0-07-0258-0.01		Android 4.3 sw 12.1.A.1.201
168	SONY Xperia T (LT30p)	A'	✓	✓	✓	✓ ₁	0-07-0258-0.01		Android 4.3 sw 9.2.A.1.205
169	SONY Xperia U (ST25i)	E	✓	✓	✓	✓ ₁			Android 4.0.4 sw 6.1.1.B.1.10
170	SONY Xperia Z (C6603)	A'	✓	✓	✓	✓ ₁	0-07-0258-0.01		Android 4.2.2 sw 10.3.1.A.2.67
171	SONY Xperia Z1 Compact (D5503)	A'	✓	✓	✓	✓ ₁			Android 4.4.4 sw 14.4.A.0.118
172	SONY Xperia Z3 Compact (D5803)	A'	✓	✓	✓	✓ ₁			Android 6.0.1 sw 23.5.A.1.29

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓₁ only from phone

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

No	Type	Set of tips	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Charger available	Article code (Charger)	Version of phone software used to test / Comments
173	Sony Ericsson Aino	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	R7BA084
174	Sony Ericsson C902	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	R3E004
175	Sony Ericsson Elm	E	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	R7CA061
176	Sony Ericsson Satio (Idou)	F	✓	✓	✓	✓ ₁	✓	0-07-0258-0.05	R1BB041
177	Sony Ericsson Xperia Arc (LT15i)	A'	✓	✓	✓	✓ ₁			Android 4.0.4 sw 4.1.B.0.587
178	Sony Ericsson Xperia Arc S (LT18i)	A'	✓	✓	✓	✓ ₁			Android 4.0.4 sw 4.1.B.0.587
179	Sony Ericsson Xperia neo V (MT11i)	E	✓	✓	✓	✓ ₁			Android 4.0.4 sw 4.1.B.0.587
180	Sony Ericsson Xperia ray	E	✓	✓	✓	✓ ₁			Android 4.0.4 sw 4.1.B.0.587
181	Sony Ericsson Xperia X10	A'	✓	✓	✓	✓ ₁			Android 2.3.3 3.0.1.G.0.75
182	Xiaomi Mi 4 LTE	A'	✓	✓	✓	✓ ₁			Android 6.0.1 MMB29M MIUI 7.3 by xiaomi.eu (6.3.24)
183	Vodafone Prime 6	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	040FCN1
184	Vodafone Smart Power 4	A'	✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	300FCN1
185	Mobiwire Dakota		✓	✓	✓	✓ ₁	✓	0-07-0258-0.01	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓₁ only from phone

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.