


Installation Manual Double DIN Kit



Take the lower part of the fascia plate and couple it with the main plate as shown in figure below.



Reassemble the remaining parts on the new fascia plate and mount the radio using mounting brackets (included)




Tighten the screw A and fix the air vents removed from the original mask using the 6 screws B as shown in figure .

All installation work must be performed by a qualified professional installer only. The manufacturer / dealer is not liable for any kind of incidental or indirect damages.

HYUNDAI I20 2012 ->

with manual climate control
Compatible with double DIN devices



Double DIN Kit contents

Facia Plate
Mounting Brackets
Screws

01/2013 ALL RIGHTS RESERVED. Technical changes possible. No liability for misprints.

All installation work must be performed by a qualified professional installer only.
The manufacturer / dealer is not liable for any kind of incidental or indirect damages.